



FIG. 1


PRIOR ART

FIG. 3





52 -54




76A

CLICK ON AN AXIS TO VIEW DETAILS

Indentation: 95% CI of Model
(for selected (z0,10))

Squared Errors
(for selected (z0,10))



Elasticity for selected (z0,10) E, Error vs. z0 over evaluated range
(Display +/- 300% of mean.) (Display +/- 300% of minimum.)





FIG. 6